



Address: Jihua 4 road,Foshan City,Guangdong Province,China Website: www.georgematerial.com


Summary						
NO.	Product Type	Unit	Quantity	Unit Price (USD)	Amount (USD)	Remarks
1	Kitchen	set	1	\$8,630.00	\$8,630.00	
2	Laundry	set	1	\$2,468.00	\$2,468.00	
3	Bar	set	1	\$1,873.00	\$1,873.00	
Total		set	3	\$12,971.00		



Part1: Kitchen (Glossy Lacquer Door + Sintered Stone Countertop + Plywood Carcass)									
---	--	--	--	--	--	--	--	--	--



Part2: Laundry (Glossy Lacquer Door + Plywood Carcass)		
---	--	--

Part2: Laundry (Glossy Lacquer Door + Plywood Carcass)



1	Laundry		cabinet (W76"xH36.13"xD15.75")	1	\$595.00	\$595.00	\$2,468.00	Laundry 1) carcass: European Grade E0 plywood faced by melamine finish Thickness:0.7" 2) door: European Grade E0 MDF faced by lacquer finish Thickness:0.7" 3) hardware: China brand soft closing hardwares
TOTAL FOR LAUNDRY IN USD					\$2,468.00			
Part3: Bar (Glossy Lacquer Door + Sintered Stone Countertop + Plywood Carcass)								
								
1	Bar		cabinet (base cabinet: W69" shelves: W60")	1	\$390.00	\$390.00	\$1,873.00	Bar-H:108" 1) carcass: European Grade E0 plywood faced by melamine finish Thickness:0.7" 2) door: European Grade E0 MDF faced by lacquer finish Thickness:0.7" 3) hardware: China brand soft closing hardwares
2		Sparse Shadow 	countertop & backsplash (countertop: W69" backsplash: W69")	1	\$1,483.00	\$1,483.00		4) countertop: Sintered stone, standard front skirt: H1.9", full back skirt: H72" thickness:0.47"
TOTAL FOR BAR IN USD					\$1,873.00			
ALL CABINETS TOTAL IN USD					\$12,971.00			
50% DEPOSIT IN USD					\$6,485.50			
BALANCE IN USD					\$6,485.50			

- Notes:
1. Delivery Term: EXW
 2. Payment terms: 50% deposit by T/T after confirming the P/I. The balance by T/T before loading.100% payment if enough stock.
 3. Order lead time: Within 30-45 days after receipt of deposit or payment and drawing confirmed.
 4. Packing: wooden box/cartons
 5. Because the camera Angle and resolution are not the same, color difference is a normal phenomenon.

